CONFIDANTAL

220005-3 25X1A

CENTRAL INTELLIGENCE GROUP

INTELLIGENCE REPORT

7095

COUNTRY China

DATE: 25X1X

info.

SUBJECT Economic Information: Condition of Railroad between Nankou and Kalgan

DIST. 29 January 1947

PAGES 2

SUPPLEMENT

ORIGIN

25X1X

BRARY COPY"

1. Nankou (116-06,40-14) to Kangchuang (115-50-40-22)

25X1X

Source traveled by train, and reports that the new stretch of track between these two towns is complete, but is of temporary construction. Bridges are made of piles of ties. Sleepers are still lacking stone fill to keep them firm; they are unevenly laid and are insufficient in number. Freight cars have been converted to telephone and wireless stations. At various points along the line source observed overturned and fire-gutted freight cars which had lain there since the previous May.

25X1X

2. Kangehuang

The railroad station is badly damaged, but is under repair. Source observed that doors and windows had been removed from the station. (He was informed by the station master that the Communists had done this. Rail instal25X1X lations were damaged. (Source was informed by the station master that this was a result both of Nationalist bombing and Communist demolitions. The letter took the form of pulling up rails and burning sleepers. There was5X1X a total of 50 cars at Kangchuang, mostly empty, but some loaded with rails and sleepers. Trains arriving from Huailai (115-45,40-20) carried both civilian and military traffic, but not full loads. The engineers who5X1X were supervising rail repairs; they appeared to source to be efficient and hardworking; one of them had had a year's experience on an American railroad. (This man said that because of the deserted condition of Kangchuang, laborers to repair the railroad have been imported from Peiping and Kalgan. Some soldiers are also being used.

25X1X 3. Kangchuang to Huailai (115-42,40-22)

a. Source, traveling by train, observed a total of about 40 cars at various points along this stretch of line. At Huailai he observed about 50 cars at the railroad station.

b. The railroad station suffered the same sort of damage as that at Kangchuang as a result of Nationalist bombings and Communist demolitions. Other buildings in the vicinity are generally undamaged except for the removal of doors and

WARNING NOTICE: THIS DISTRIBUTION LISTING MUST BE

Document No.

NO CHANGE IN Class.

This docume EXCISED BEFORE PUBLIC RELEASE OF THIS DOCUMENT,

PROCESSIFIED

Class. CMANGED TO:

DA REG. 27/1763

Date: 17 APRAParayed of Present Series Intelligence to the Archivist of the United States to the Date: 2008

Approved For Release 2001/03/17 : CIA-RDP82-00457R000300220005-3

CONFIDENTIAL
CENTRAL LATELATORNOCE OROUP

25X1A

25X1X

Huailai to Haiahuayuan (115-15,40-28)

Trains are apparently not running along this stretch, as source made the trip

25X1X by truck.

this stretch of
this stretch of
railroad was "only about one-fourth destroyed", and was not so bad as the
part between Hsiahuayuan and Hsuahua. He stated that a gang of repairmen
is working from Huailai toward Hsiahuayuan and hopes to meet a similar gang
which is working eastward from Hsuahua toward Hsiahuayuan. He further stated
that repairs made to date are purely of an emergency character, the bridges
being temporary ones. Permanent restoration will have to await some indefinite

25X1X future date. At issahuayuan the railroad station and yard sustained the same sort of damage as previously observed at other rail towns. The water tower is toppling badly.

25X1X

Hsiahuayuan to Hsuanhua (115-01,40-37)

25X1X

had some opportunity to observe the railroad en route. Many of the bridges were blown; many rails pulled up; many
power poles knocked down, burned, or smashed; power lines were cut; ties were
burned, or in some cases simply removed and placed in piles. (Persons in the
area stated that the "ommunists had done this with the intention of burning
them, but for some reason failed to set them on fire.

Reference is made to the statement of the engineer in paragraph 4.) Source
observed that the railroad was undergoing repairs. Many gangs of repairmen
were in evidence, and laborers were seen cutting down trees for ties. Trainloads of ties and rails and truckloads of repair materials were in evidence.
The railroad stations at Hsuanhua and Shalingtzu (114-56,40-41) are badly
damaged.

25X1X

Kalgan to Tatung

According to the engineer reported in paragraph 2, this line is severely damaged and restoration will require two months. Gange are working from both directions. Host of the rails can be unbent, but some new rails and sleepers will be required.

CONFIDENTIAL